



Posts	Bearing trees	Inches diam.	boards they bear	Links dist.	Quality of the Sail.

Posts	Bearing trees	Inches diam.	Courses they bear	Links dist.	Quality of the Soil.
A					
B					
C					
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					
O					
P					
Q					
R					
S	Post no bearing trees				
T	Post no bearing trees				
U	Post no bearing trees				
V					
W					
X					
Y					
Z					

Corners on the Indian Boundary.				
Between sections	Bearing trees	Arches diam.	Courses they bear	Links dist.
2	Mount. S. 75° North		of the corner	
8	Post no bearing		trees	
21 & 32	Post no bearing		trees	




Township N.º XVII North, Range N.º X West of 2.nd Mer. Surveyed by W.^m Harris, 1816.

Description of the Soil on the interior Sectional lines.

31 P 32	Prairie - rich, dry and good for farming			
---------	--	--	--	--

Quality of the Soil, Timber, &c. on the Township Lines.

Corner on the Vermillion River



Surveyed in 1821 by J. B. McCall, Deputy Surveyor.

Scale 40 Chains to an Inch.

I certify that the above is a true copy of the Original plat in this Office.

Surveyor General's Office.

Delant Nov. 1. 1849.

Lucius Lyon, Sur. Gen.